

AIRTEX[®] and AIRTEX[®] plus

Care and cleaning instruction

Care:

Products manufactured from Valmex[®] airtex[®] must be thoroughly cleaned and dried before storing in clean, dry and well ventilated conditions.

Wrong storage conditions can lead to biological or mildew attack which can affect the stability of the material.

Cleaning:

It can be cleaned by hand using a soft sponge with lukewarm water (approx. 30 Deg C) using a mild washing powder for delicate fabrics. After washing, the material must be completely dried. Also cleaning in an Industrial Washing Machine with drying afterwards is possible for large panels.



Mehler Texnologies GmbH

Edelzeller Strasse 44
D-36043 Fulda
Tel. +49 (0) 661 103 0
Fax +49 (0) 661 103 582

Rheinstrasse 11
D-41836 Hückelhoven
Tel. +49 (0) 2433 459 0
Fax +49 (0) 2433 459 151

info@mehler-texnologies.com · www.mehler-texnologies.com